



04 Dec 2002 05 nov 10



soldering side:

component side:



these are trim pots. The value is labelled (5k, 100k, or 500). They need to be tweaked by the tweaker AFTER you're done with everything on the board.



One of the pins will not get connected to anything.



2005-11-10
changed from battery to powerjack

Inside wiring

